CRAIGMONT MINES LIMITED

ASSESSMENT REPORT

OF

WORK

ON THE

ORANGE GROUP OF MINERAL CLAIMS

LOCATED 10 MILES NORTH WEST OF MERRITT, B.C.

N 50°10'


E 120°55'

NICOLA MINING DIVISION

G.R. SANFORD GEOLOGIST

MINERAL RESOURCES BRANCH

ASSESSMENT REPORT




ASSESSMENT REPORT OF WORK ON THE ORANGE GROUP OF MINERAL CLAIMS

TABLE OF CONTENTS	<u>PAGE</u>
Statement Of Expenses	4
Description Of Claims	5
Location and Access	6
Topography	6
Description Of Work Done	6
Conclusions	6
Statement Of Qualifications	10
Appendix	

GROUP OF MINERAL CLAIMS

LIST OF ILLUSTRATIONS	PAGE
Index Map	Preface
Claim Map - Orange Group	3
Table #1 - Drill Hole Co-ordinates	7
Tailings Dam Test Holes - Plan	8
Tailings Dam Test Holes - Section	9



GROUP OF MINERAL CLAIMS

STATEMENT OF EXPENSES

Triconing of 4 drill holes into bedrock under contract to Connors Drilling Limited 7 - 10 December, 1976	\$1,378.00
Water supply for drilling - Craigmont	50.00
Survey of drill holes, profile Craigmont Personnel, 10 Dec., 1976	50.00
Supervision G.R. Sanford 7 - 10 Dec., 1976	100.00
Report preparation G.R. Sanford I day @ \$100.00	100.00
Total	\$1,678.00

GROUP OF MINERAL CIAIMS

DESCRIPTION OF CLAIMS

The Orange Group of fourteen Located Mineral Claims and Fractions, owned by and operated by Craigmont Mines Limited, is located approximately ten miles northwest of Merritt, B.C. These claims cover a portion of Craigmont's tailings pond.

The individual claims, record number and due date are as follows:

Claim	Record Number	Date Due
Pond 0-Pond 7	59780 - 59787	28 February
Rolf 1, Rolf 2	59776 , 59777	28 February
Rolf 3Fr, Rolf 4Fr	59778 , 59779	28 February
Rolf 5	59879	7 March
Rolf 6Fr	5988 0	7 March

GROUP OF MINERAL CLAIMS

LOCATION AND ACCESS

The Orange Group of Mineral Claims was staked by Craigmont Mines Limited in early spring 1974, to cover portions of the Craigmont tailings pond, and ground to the east and west which had become open. Aberdeen Road, connecting the mine and Lower Nicola, crosses the eastern portion of the claims.

TOPOGRAPHY

The entire claim group lies on the floor of the gravel filled valley of Stumbles Creek. The Craigmont tailings dam extends 4000 feet across this valley, creating a basin into which mine tailings are pumped. Stumbles Creek was diverted to the west, around the tailings pond, and now flows along the base of a bedrock scarp at the western edge of the valley. Vegetation is typical dry interior pine forest.

DESCRIPTION OF WORK DONE

When the Craigmont tailings dam increases to its' ultimate height, it will probably be necessary to re-direct Stumbles Creek so as to prevent dam failure from a wash out. In order to assess the various alternatives, it was necessary to determine the depth to bedrock near the western abutment of the tailings dam.

The depth to bedrock was determined in four locations by using a truck mounted long Year 38 diamond drill. Holes were drilled using a 3½ inch tricone bit through the overburden and Penetrated at least five feet into bedrock. No coring techniques were used. The results are as tabulated in Table 1. Nole positions were surveyed by stadia. Hole positions are plotted on plan and section on Drawings 1 and 2.

The drilling was done under contract by Connors Drilling Limited from December 7 to 10, 1976. All holes were collared on the Pond 5 mineral claim, owned and operated by Craigmont Mines Limited.

CONCLUSIONS

The death to bedrock was established along section A-A. This will provide information for future planning. The Department of Mines will be advised of the various alternatives for dealing with Stumbles Creek when all studies are complete.


G.R. Sanford


Senior Mine Geologist

TABLE #1
DRILL HOLE CO-ORDINATES

	LATITUDE	DEPARTURE	COLIAR ELEVATION	DEPTH TO BEDROCK	DEPTH OF HOLE	ELEVATION OF BEDROCK	REMARKS
Hole #1	921.04	5182.94	699.99	3.96	6.10	696.03	3.96-5.18 Broken
Hole #2	948.52	5170.86	700.44	3.96	6.40	696.48	
Hole #3	989.12	5167.34	699.16	11.89	13.72	687.27	
Hole #4	965,22	5171.71	698.86	7.01	10.06	691.84	7.01-8.53 Soft
Bedrock ln Diteb	915.63	5178.62	697.64				
Bedrock In Ditch	937.61	5172.18	697.82				

~!





STATEMENT OF QUALIFICATIONS

I, Cerald R. Sanford, of 2213 Quilchena Avenue, Merritt, B.C. state that

- 1) I graduated from the University of British Columbia in 1969, obtaining a Bachelor of Applied Science Degree in Geological Engineering.
- 2) I am registered as an Engineer in Training with the Association of Professional Engineers of British Columbia.
- 3) I have been continuously employed in the mining industry since graduation from University.
- 4) I am currectly employed by Craigmont Mines Limited as the Senior Mine Geologist at the Merritt mine site.

G.R. Sanford, Senior Mine Geologist

10 February, 1977

APPENDIX

CONTRACTORS STATEMENT



204 - 1201 WEST PENDER STREET, VANCOUVER, B.C. CANADA V6E 2V2
AREA CODE 604/683 - 2222

•	INVOICE	No: 7364
Craigmont Mines L P.O. Box 3000	td. DA	December 16/76
Merritt, B.C.		
•	SURFACE DIAMOND DRILLING	
•	SOILS WORK	•
	MERRITT, B.C.	
	DECEMBER 7 - 10, 1976	
FIELD COST WORK	6 DELIZER	•
DATE SHIFT HOUR		
Dec. 7/76 8 4 8 8	▲	
8 8 9 8	Sampling	
10 8-4-	Sample and move off	1,200.00
	ift hours @ 50.00	1,600.00
24	11 MOULD & 50.00	
SUPPLIES CONSUMED	. •	
1 34" Tricone Bit	86.00	·
l piece BW - 10' casi	nig 48.90	
l piece BW 2' casing	16.15	
	151.05	
	Plus 7% 10.57	
	Plus 10% 16.16	177 70
	F1us 106 10.16	177.78 1 ,777.78
		•
	ORDER No.	1.377.78
TOTAL FOOTAGE 119'		GK1
	RECEIVED BY) 7
	DATE	
	CHECKED WITH ORDER	
	CHECKES WITH COLUMN COL	CHARLES 13
	EXTERMIONS CHECKED	CITARLE (0)
REVISED	PRICE / 17900/80 0/6 320 Dec 76	
1-2	APPROVED FOR PAYMENT	
	VOLVOARD 1 20: 13 (13 (13 (13 (13 (13 (13 (13 (13 (13	
1	CHATCED TO	7.264